

Anti-Icing photos.

The following photos were taken in the eastern part state of Washington near the Columbia River on Highway 243. Even though the details of what product was applied, or how much, they are excellent examples of what “anti-icing” can accomplish. Note the ice on the shoulders and on the side road where anti-icing was not accomplished.



Photo 1. Note the ice outside of the application area on both sides of the highway



Photo 2. Note ice on shoulders and edge of roadway near edge lines. Just outside of the application area.



Photo 3. Close up of ice on shoulder just outside of application area.



Photo 4. More icy shoulders with bare and wet road. Bare road is due to anti-icing application



Photo 5. Note ice on side road that was untreated.



Photo 6. Note ice on untreated side road. Also note tracking of material and melting action on the side road.



Photo 7. Untreated and icy side road.



Photo 8. Untreated and icy side road.



Photo 9. Untreated and icy side road.